



DEPARTURE ROUTE DESCRIPTION

TAKE-OFF RUNWAY 33: Climb heading 340° to 9100, then a climbing left turn to 16000 heading 270° to intercept I-PKN NW course outbound to LINDZ INT/DBL 13 DME. Then via assigned transition. Maintain 16000, expect clearance to filed altitude 10 minutes after departure.

LOST COMMUNICATIONS: If no transmissions are received for one minute after departure, turn left heading 270° to intercept and proceed via the I-PKN NW course (outbound) to LINDZ INT/DBL 13 DME, then via assigned route/transition.

GRAND JUNCTION TRANSITION (LINDZ5.JNC): From over LINDZ INT via DBL R-244 and JNC R-060 to JNC VOR/DME.

KREMMLING TRANSITION (LINDZ5.RLG): From over LINDZ INT via SXW R-196 to SXW VOR/DME; then via SXW R-001 and RLG R-260 to RLG VOR/DME.

MEEKER TRANSITION (LINDZ5.EKR): From over LINDZ INT via DBL R-244 and RIL R-151 to RIL VOR/DME; then via RIL R-331 and EKR R-148 to EKR VOR/DME.

RED TABLE TRANSITION (LINDZ5.DBL): From over LINDZ INT via DBL R-244 to DBL VOR/DME.

RIFLE TRANSITION (LINDZ5.RIL): From over LINDZ INT via DBL R-244 and RIL R-151 to RIL VOR/DME.

SW-1, 22 OCT 2009 to 19 NOV 2009

SW-1, 22 OCT 2009 to 19 NOV 2009